

Stock: 30003198

Unit:

Customer:

Lot:



Date: 06/22/2016 2:17 PM
 Seller: GENERAL SERVICES
 ADMINISTRATION/OFA #G93791
 Phone/Fax: (0) -(0) -
 Sale Date:

Year 2012	Make FORD	Model EXPLORER BASE	Body Type SPORT UTILITY VEHI	VIN 1FMHK8B81CGA21414
Drive 4WD	Ext Color Blue	Int Color Gray	Int Material Cloth	Sound Satellite
Fuel Gas	Mileage 108214	Odo. Type Digital	Engine 6-Cyl. 3.5Liters	Transmission Automatic
Doors 4	License Plate	License St	Plates	Plate Expires
				End of Term

- Accessories:** Remote key (2)
- Interior:** Seats, (7) Power mirrors, Child seat anchors, Steering wheel controls, Power driver seat, Power locks, 5 passenger seating, Seat type 60/40, Power windows, Cruise control, Tilt wheel, Owners manual, Odometer scale, (Miles) Steering wheel audio controls, Rear defroster, Safety restraint system
- Exterior:** Alloy wheels, Fog lights, Towing package, Rear wiper, Spare tire, Luggage rack, Tinted windows, Trailer hitch, Rear tail/lift gate
- Equipment:** Antilock brake system, Power steering, Vehicle skid control, Power brakes, Air conditioner, Adaptive ride package, Steptronic transmission, Telescopic steering wheel, Side air bags, Hill descent control
- Electronics:** Cd player, Security alarm, Mp3 player, Trip computer, Traction control, Radio-satellite

Notification:

Arrival: 06/22/2016

Visual: 06/22/2016

Body: 06/22/2016

Mechanical: 06/22/2016

Writer: MMCCLAIN

Complete: 06/22/2016

Revised:

Driveable: Yes

Visual Frame

Damage:

Book Value: \$12700.00

Condition: 3.4

Tires	Left	Right
Front	02/32in Goodyear 17	02/32in Goodyear 17
Rear	06/32in Goodyear 17	06/32in Goodyear 17
Spare		



Announcements:

Notes:

- BASE

Inspection Date	Description	Approved	Repaired	Material Estimate	Labor Hours	Labor Estimate	Paint Hours	Paint Estimate	Sublet Estimate
<i>Chargeable</i>									
06/22/2016	Front bumper cracked - Replace.			300.00	0.00	0.00	0.00	0.00	0.00
06/22/2016	Hood rust - SURFACE DAMAGE. Refinish.			150.00	0.00	0.00	0.00	0.00	0.00
06/22/2016	Lf door mult dents/no paint - DENTS,CHIPS. Less lin. Repair.			100.00	0.00	0.00	0.00	0.00	0.00
06/22/2016	Lf fender dent/paint dmg			125.00	0.00	0.00	0.00	0.00	0.00

	- DENT WITH DAMAGE,PLUS SCRATCH TOUCHUP. 1 - 3in. Repair.						
06/22/2016	Lf mirror housing mult scratches/heavy - 1 - 3in. Touch Up.	75.00	0.00	0.00	0.00	0.00	0.00
06/22/2016	Lr door scratch heavy - 6 - 9in. Touch Up.	75.00	0.00	0.00	0.00	0.00	0.00
06/22/2016	Rear bumper mult scratches/heavy - 3 - 6in. Touch Up.	75.00	0.00	0.00	0.00	0.00	0.00
06/22/2016	Lift gate rust - Touch Up.	75.00	0.00	0.00	0.00	0.00	0.00
06/22/2016	Rr bumper guard torn - TOW HITCH BUMPER TRIM COVER PANEL. Replace.	65.00	0.00	0.00	0.00	0.00	0.00
06/22/2016	Rf door mult dents/no paint - DENTS,CHIPS. 1 - 3in. Repair.	100.00	0.00	0.00	0.00	0.00	0.00
06/22/2016	Rr door mult dents/no paint - DENTS,CHIPS. Less 1in. Repair.	100.00	0.00	0.00	0.00	0.00	0.00
06/22/2016	Rr door mult scratches/heavy - 3 - 6in. Touch Up.	75.00	0.00	0.00	0.00	0.00	0.00
06/22/2016	R qtr panel mult scratches/heavy - 9 - 12in. Refinish.	150.00	0.00	0.00	0.00	0.00	0.00
<i>Subtotal:</i>		\$1465.00	0.00	\$0.00	0.00	\$0.00	\$0.00
<i>Deductible</i>							
<i>Subtotal:</i>		\$0.00	0.00	\$0.00	0.00	\$0.00	\$0.00
<i>Nonchargeable</i>							
<i>Subtotal:</i>		\$0.00	0.00	\$0.00	0.00	\$0.00	\$0.00
Total Estimate:		\$1465.00	0.00	\$0.00	0.00	\$0.00	\$0.00
Grand Total:						\$1465.00	

Charge Date	Description	Amount
06/22/2016	Pick-up charge	140.00
06/22/2016	Auto ims fee	12.50
Total Charges:		\$152.50




Front right



Dash




Engine



Interior front



Extra-photo



Extra-photo



Wheel



Rear left



Front bumper cracked




Rear r bumper guard
torn



Front hood rust



Rear lift gate rust



Lf side fender dent/paint
dmg



Rr side qtr panel mult
scratch



Rear right



Extra-photo

INDIANA AUTO AUCTION

4425 W WASHINGTON CTR RD, FORT WAYNE IN, 46818

(260) 489-2776

30003198